



**DORNER<sup>®</sup>  
SERVICES**


**DORNER<sup>®</sup> FIT<sup>™</sup> PROGRAM**

FACTORY INSPECTION & TRAINING

# DORNER<sup>®</sup>

**MOVE FAST. MOVE SMART.**

# C U S T O M



## **Get FIT<sup>™</sup>**

### **NEW CONVEYORS & PROJECTS**

The FIT<sup>™</sup> Squad Technicians will ensure conveyor performance on the first day of operation.

- Ensure proper installation
- Review safety
- Tune product handling
- On-site training
- Recommend spare parts
- Resolve warranty issues

## **INSTALLATION AND START-UPS**

### **ENSURE SYSTEM PERFORMANCE**



- Faster installs
- Project management
- Avoid warranty issues
- On-site training

## **STOCK REPLACEMENT PARTS AND BELTS**

### **WHEN TOMORROW IS TOO LATE**



- Increase system reliability
- Maintain warranty
- Upgrade technologies
- 24 hour shipping

For more information, part ordering or to schedule a FIT<sup>™</sup> v

# D O R N E R B E N E F I T S

## **Stay FIT™**

### **EXISTING EQUIPMENT**

The FIT™ Squad Technicians will conduct an assessment of your existing packaging and processing conveyors for optimum system reliability.

- Review wear parts
- Evaluate product handling
- Review safety
- Suggest upgrade possibilities
- Evaluate replacement part inventory



## **CUSTOMER MAINTENANCE TRAINING**

### **GET HANDS-ON EXPERIENCE**



- Preventative and service maintenance
- Belt changing and splicing
- Evaluate service part requirements
- Improve product handling

## **RE-PURPOSE EXISTING CONVEYORS**

### **MEET NEW MANUFACTURING NEEDS**



- Aid in the design of new layouts
- Re-purpose recommendations
- Suggest and perform upgrades
- Re-install conveyors



Dorner's Services are delivered by a team of conveyor experts, the FIT™ Squad Technicians. With over 20 years in the conveyor industry, they have the experience and trained eye that will save you time and money.

For more information, part ordering, or to schedule a FIT™ visit, go to [www.dorner.com/service/](http://www.dorner.com/service/), or call at 800-397-8664.

## Ensure proper conveyor installations with "Get FIT™" visits...

A candy company was experiencing significant motor wobble and was concerned that the vibration would shake the new 5200 conveyor apart. The company contacted Dorner Services to set up a Get FIT™ visit to evaluate and fix the problem before the line was operational.

During the visit, the FIT™ Squad Technician discovered that the installation was flawed not the conveyor. The company had bolted the conveyor to the floor but the drive end of the conveyor was not level. The technician leveled the conveyor and the motor wobble was eliminated.

At the same time, the FIT™ Squad Technician inspected the other conveyors on the line, tuned product transfers, trained the maintenance staff and suggested key replacement parts. As a result, the new line started up on time at optimal performance and operational efficiency.

Because conveyors are considered simple and require minimal maintenance, proper conveyor set up is often overlooked. To minimize maintenance time, increase production and avoid warranty claims schedule a Dorner FIT™ visit on your new and existing processing conveyors today.

– A Specialty Candy Company

## Can you afford not to have a "Stay FIT™" assessment?

On a recent Stay FIT™ assessment, the FIT™ Squad Technician evaluated a large paper company's conveyors. The technician uncovered a center drive conveyor that was buried in a packing machine. The tech learned that the last belt change took the maintenance team 10 hours equal to \$30,000 in lost production time.

The FIT™ Squad Technician, through training and some minor conveyor changes, was able to reduce the belt

change time to ½ hour or equal to \$1,500 in loss production time— a customer savings of over \$28,000 in production time on every belt change.

The technician also evaluated the customer's replacement part inventory to ensure continuing conveyor reliability and the shortest downtime possible for this 24/7 operation.

– A Large Paper Company

**DORNER**®

DORNER MFG. CORP.  
PO Box 20 • 975 Cottonwood Ave.  
Hartland, WI 53029 USA

INSIDE THE USA  
TEL: 800.397.8664  
FAX: 800.369.2440

OUTSIDE THE USA  
TEL: 262.367.7600  
FAX: 262.367.5827

[www.dorner.com](http://www.dorner.com)

851-684 REV. A HGI-2.5M-0409